Appendix C

Technical Review Committee (TRC) Conditions

Appendix C

City Technical Review Committee Conditions

Project Name and Number: Serenola Manor, DB-16-48 SPA

Reviewing Board: City Development Review Board

Public Hearing Date: 10/31/2017

	aring Date:	04-4	Development	Cuanahat	Fitz Control	Maylery Name	Changement C. bla-4	Changemark Details	Markup Date	Updated By	Applicant Respons
Cycle 2	Complete? False	Status Unresolved	Department Real Estate	Snapshot	File 16-0045-L1-LANDSCAPE.pdf	Markup Name GRU Real Estate	Changemark Subject Proposed Tree Too Close to O/H Electric	This proposed tree may be too close to the existing O/H electric line. Please verify with GRU Electric Engineering	09/25/2017 11:50 AM	Tiffany Davis	Applicant Respons
2	False	Unresolved	Real Estate	CE	16-0045-L1-LANDSCAPE.pdf	GRU Real Estate	Tree Canopy in Easement	As a heads up, you may want to move the proposed trees back a little. The proposed tree canopy that extends into	09/25/2017 11:50 AM		
2	False	Unresolved	Real Estate		16-0045-L1-LANDSCAPE.pdf	GRU Real Estate	Several Proposed Trees Shown in PUE over UGE	There are several trees shown in the easement over the UGE. Please show the revised easement dimensions			
2	False	Unresolved	Real Estate	نيات	16-0045-L1-LANDSCAPE.pdf	GRU Real Estate	Per W/WW - Trees Too Close to WM		09/25/2017 11:50 AM		
2	False	Unresolved	Real Estate		16-0045-C-200 GRADE UTILITY.pdf	Real Estate	Show and label ROW of SW 41st Lane		09/25/2017 11:45 AM	Tiffany Davis	
2	False	Unresolved	Real Estate	The	16-0045-C-200 GRADE UTILITY.pdf	Real Estate	PUE Line Needs to End at ROW Line		09/25/2017 11:45 AM	Tiffany Davis	
2	False	Unresolved	Real Estate		16-0045-C-200 GRADE UTILITY.pdf	Real Estate	Reduce PUE Size for U/G Electric	The PUE over the UGE line can be reduced to 10' over the path of the line and a 10' x 10' square around the TX, per	09/25/2017 11:45 AM	Tiffany Davis	
2	False	Unresolved	Water-Waste Water	信型	16-0045-L1-LANDSCAPE.pdf	www	W/WW Comment sheet L1	Trees shall be a min. of 7.5' from GRU water.	09/19/2017 3:31 PM	Christina DeStephens	
2	False	Unresolved	Transportation Mobility	372	16-0045-C-100 SITE.pdf	Sidewalk connection	Changemark note #01	 Please consider a sidewalk connection from the building in the northwest part of the site to the sidewalk along SW 41st 		Jason Simmons	
2	False	Unresolved	Transportation Mobility		16-0045-C-000 COVER.pdf	TMPA Notes	Changemark note #01	Please add a note to the site plan that states this development must meet one Transportation Mobility	09/19/2017 9:30 AM		
2	False	Unresolved	Transportation Mobility		16-0045-C-000 COVER.pdf	TMPA Notes	Changemark note #02	Please add to the concurrency note on the plan that this development will meet the applicable Transportation	09/19/2017 9:30 AM	Jason Simmons	
2	False	Unresolved	Public Works - Design		16-0045-C-100 SITE.pdf	RM	Right-of-way pavement detail	2" thick asphalt must be used within City right-of-way.	09/19/2017 8:41 AM		
2	False	Unresolved	Public Works Stormwater		16-0045-C-010 NOTES DEMO.pdf	PW-storm	driveway culvert	Will this culvert be replaced?	09/13/2017 1:48 PM		
2	False	Unresolved	Public Works Stormwater		16-0045-C-000 COVER.pdf	PW-storm	Updated info	These elevations changed in the drainage design notes, please correct.	09/13/2017 9:45 AM		
2	False	Unresolved	Urban Forestry		16-0045-L1-LANDSCAPE.pdf	Earline	Nandina Domestica -Heavenly Bamboo	Please replace the Heavenly bamboo because it is listed as a category 1 from the Florida Exotic Pest Plant Council's list.	09/12/2017 10:31 AM	Earline Luhrman	

Appendix C

City Technical Review Committee Conditions

2	False	Unresolved	Planners		16-0045-C-000 COVER.pdf	Current Planning - Massey	Sheet C-000 (Project Description/Density)	Since the first submittal, the site acreage has been changed to 1.45 acres. As a result, the remaining	09/07/2017 11:46 AM	Bedez Massey	
2	False	Unresolved	Planners		16-0045-C-000 COVER.pdf	Current Planning - Massey	Sheet C-000 (Development Data)	The height, number of stories and gross floor area must also inloude the existing single-story dwelling.	09/07/2017 11:46 AM	Bedez Massey	
2	False	Unresolved	Planners		16-0045-E1-PHOTO.pdf	Current Planning - Massey	Photometric Plan	Please correct the spelling of "courtyard" within the lighting narrative.	09/07/2017 4:49 PM	Bedez Massey	
2	False	Unresolved	Planners		16-0045-E1-PHOTO.pdf	Current Planning - Massey	Photometric Plan	To facilitate board consideration of a lighting waiver from the City's lighting requirements, the applicant	09/07/2017 4:49 PM	Bedez Massey	
2	False	Unresolved	Planners	Charles on the state of the sta	16-0045-E1-PHOTO.pdf	Current Planning - Massey	Photometric Plan	The height of luminaires in the off-street parking lot can't exceed 15 feet w/n 75 feet of adjacent residential property.	09/07/2017 4:49 PM	Bedez Massey	
2	False	Unresolved	Planners		16-0045-E1-PHOTO.pdf	Current Planning - Massey	Photometric Plan	The manufacturer's cut-sheet for building exterior lighting must be provided to show compliance with the City's	09/07/2017 4:49 PM	Bedez Massey	
2	False	Unresolved	Planners	المقاع	16-0045-E1-PHOTO.pdf	Current Planning - Massey	Photometric Plan	The photometric plan must show that the average vertical illuminance measured five feet above the height of liminaires	09/07/2017 4:49 PM	Bedez Massey	
2	False	Unresolved	Planners	ETEK.	16-0045-C-100 SITE.pdf	Current Planning - Massey	Site Plan	A sidewalk from Building 1 to proposed sidewalks in public right-of-way is highly recommended. If not from the	09/21/2017 4:41 PM	Bedez Massey	
2	False	Unresolved	Planners	ZEC	16-0045-C-100 SITE.pdf	Current Planning - Massey	Sheet C-100 (Building Setbacks)	Please provide a building tie- down, along with the dimension separating the proposed building from the	09/21/2017 4:41 PM	Bedez Massey	
2	False	Unresolved	Planners	层配	16-0045-L1-LANDSCAPE.pdf	Current Planning - Massey	Landscape Plan	The wall(s) of Building 1 cannot encroachment into the 25 ft. building setback, and the roof overhang cannot	09/07/2017 4:54 PM	Bedez Massey	
2	False	Unresolved	Planners		16-0045-L1-LANDSCAPE.pdf	Current Planning - Massey	Landscape Plan	Additional shrubs are required along the off-street parking lot (west side) to screen the parking lot from the adjoing	09/07/2017 4:54 PM	Bedez Massey	
2	False	Unresolved	Planners		16-0045-L1-LANDSCAPE.pdf	Current Planning - Massey	Landscape Plan	Foundation shrubs are recommended to enhance the view of the back of Building 1 from SW 31st Drive.	09/07/2017 4:54 PM	Bedez Massey	
1	False	Unresolved	Planners	Linke	16-0045-Z-ARCH-EXISTING HOUSE.pdf	Current Planning - Massey	Floor Plan	The floor plan must be made consistent with the updated boundary survey.	06/29/2017 5:36 PM	Bedez Massey	The site plan shows the updated boundary data. The floor plans apply to more than one of the buildings on the site and are
1	False	Unresolved	Planners	of testings	16-0045-Z-ARCH-8 PLEX ELEVATIONS.pdf	Current Planning - Massey	Building Height	Please provide the building hegiht, per Article II of the City Land Development Code, showing points of reference.	06/29/2017 5:34 PM	Bedez Massey	See the revised building elevations and the building height note on C-000.
1	False	Unresolved	Planners		16-0045-Z-ARCH-8 PLEX ELEVATIONS.pdf	Current Planning - Massey	Angle-of-light	Please label the property line and show the angle of light setback.	06/29/2017 5:34 PM	Bedez Massey	See the site plan for both the property line and the angle of light setback. The eave height is now shown on the building elevations for
1	False	Unresolved	Planners		16-0045-Z-ARCH-8 PLEX ELEVATIONS.pdf	Current Planning - Massey	Angle of Light	Label property line and show angle of light setback.	06/29/2017 5:34 PM	Bedez Massey	See the site plan for both the property line and the angle of light setback. The eave height is now shown on the building elevations for
1	False	Unresolved	Planners	Total and	16-0045-Z-ARCH-6 PLEX ELEVATIONS.pdf	Current Planning - Massey	Building Height	Please provide the building height, per Aricle II of the City Land Development Code, showing points of reference.	06/29/2017 5:31 PM	Bedez Massey	See the revised building elevations and the building height note on C-000.