



Legislation Details (With Text)

File #: 001395 **Version:** 0 **Name:** Final Report of Northeast Park Stormwater Task Force (B)

Type: Discussion Item **Status:** Passed

File created: 6/11/2001 **In control:** Advisory Boards and Committees

On agenda: **Final action:** 6/11/2001

Title: Final Report of Northeast Park Stormwater Task Force (B)

Sponsors:

Indexes:

Code sections:

Attachments: 1. 001395_Master Report_20010611, 2. 001395_Mayor and Commissioners_20010611, 3. 001395_Monica Cooper_20010611, 4. 001395_NE Park and NeE 2nd St Map_20010611, 5. 001395_NE Park Stormwater Task Force_20010611, 6. 001395_Shaklee Health Alternatives_20010611, 7. 001395_Text File_20010611

Date	Ver.	Action By	Action	Result
6/11/2001	0	City Commission	Approved, as shown above - See Motion(s)	Pass

Final Report of Northeast Park Stormwater Task Force (B)

The Task Force held five meetings, with their final meeting being May 29, 2001.

The Task Force developed the following seven recommendations:

1. Northeast Park is far too valuable for stormwater management use. Therefore, no part of Northeast Park should be used for this purpose. In order to deal with stormwater quantity and quality issues generated in the Northeast Park watershed, we recommend a step-down treatment approach that includes sites #8, #4, and #2 of sufficient size to substantially improve stormwater runoff characteristics prior to discharge into Sweetwater Branch.
2. Due to the fact that the adjacent western watershed is the primary contributor to the Sweetwater Branch stormwater runoff problems, we recommend that the City take decisive action in addressing and correcting the stormwater drainage problems that contribute to Sweetwater Branch, recognizing that flooding caused by the western watershed affects the Northeast Park watershed dynamics. Furthermore, we recommend the City investigate sites A and B or similar solutions for correcting this problem.
3. We recommend that the City adopt stronger redevelopment stormwater policies and regulations to avoid what has occurred with the redevelopment of the Gainesville Shopping Center Publix. This redevelopment does not include adequate stormwater management facilities to fully treat stormwater runoff.
4. We recommend that the City offer incentives to existing businesses to provide stormwater management facilities or to reduce the amount of impervious surfaces on their property in order to improve stormwater runoff quantity and quality of discharge.
5. We recommend that no major recreational facilities, such as the proposed skateboard facility (since withdrawn), be added to Northeast Park. However, we recommend the following improvements:

- a. A water fountain near the picnic area.
- b. Additional picnic tables.
- c. Additional sitting benches.
- d. Additional shade trees in the playground area.

All of the above should be accomplished maintaining the aesthetic quality of the park.

6. We recommend that old playground equipment be examined by qualified experts and the equipment and the sites they occupy be brought up to recognized standards for safety.

7. At the end of the six month trial period of the dog park, we recommend the City survey the park users (including children) as to the dog park's usefulness and location to determine its viability in its current location.

No funding impacts have been determined at this time.

The City Commission accept the Northeast Park Stormwater Task Force report.