

City Commission

Appeal

April 2, 2015

Demolition of a single structure at 1227 NW 4th Avenue



PAUDOEAUX HEWETT, & WALPOLE, IND.

Civil Engineering Land Surveying Land Planning Construction Engineering Inspection

1227 NW 4th Avenue Certificate of Appropriatenss





- 1. The historic or architectural significance of the building, structure or object;
- 2. The importance of the building, structure or object to the ambience of a district;
- 3. The difficulty or the impossibility of reproducing such a building, structure or object because of its design, texture, material, detail or unique location;
- 4. Whether the building, structure or object is one of the last remaining examples of its kind in the neighborhood, the county or the region;
- 5. Whether there are definite plans for reuse of the property if the proposed demolition is carried out, and what the effect of those plans on the character of the surrounding area would be;
- 6. Whether reasonable measures can be taken to save the building, structure or object from collapse; and
- 7. Whether the building, structure or object is capable of earning reasonable economic return on its value.



- 1. The historic or architectural significance of the building, structure or object;
- 2. The importance of the building, structure or object to the ambience of a district;

STATE OF FLORIDA DEPARTMENT OF STATE Division of Archives, History	FLORIDA MASTER SITE FIL	
and Records Management	Site Inventory Form	FDAHRM 802 = =
1101-01	Site 830 = = Si 4 Ave, Gainesville, Fla. 3260	No. 201573 urvey Date 8007 820 = = 01 905 = =
Significance: This house contributes	s in scale and character to t	he Fifth Avenue neigh-
common bond brick hous	evolving since the mid-nine se is period revival cottage	with classical
entablature. The how	surround is made up of two C use is located in Shellie Cou x assessor's reported date of	rt which was platted in



Demolition. A decision by the historic preservation board approving or denying a certificate of appropriateness for the demolition of buildings, structures or objects other than those in the Pleasant Street Historic District shall be guided by:

3. The difficulty or the impossibility of reproducing such a building, structure or object because of its design, texture, material, detail or unique location;

Significance:

This house contributes in scale and character to the Fifth Avenue neighborhood which has been evolving since the mid-nineteenth century. This common bond brick house is period revival cottage with classical tendencies. The door surround is made up of two Corinthian pilasters with entablature. The house is located in Shellie Court which was platted in 1935, although the tax assessor's reported date of construction is 1933.

✓ There is <u>no difficulty reproducing common bond brick</u> buildings, structures, or objects with this common design, texture, material, detail, and location.



Demolition. A decision by the historic preservation board approving or denying a certificate of appropriateness for the demolition of buildings, structures or objects other than those in the Pleasant Street Historic District shall be guided by:

4. Whether the building, structure or object is one of the last remaining examples of its kind in the

neighborhood, the county or the region;

✓ Several remaining examples of similar buildings exist in the neighborhood, the County, and the region (as shown, examples of other homes on the same block).





- 5. Whether there are definite plans for reuse of the property if the proposed demolition is carried out, and what the effect of those plans on the character of the surrounding area would be;
- √ The site has an approved Planned Use District (PUD) and a Planned
 Development (PD), which authorizes a mixed-use multi-story building
 program. The City's Historic Preservation Board, Plan Board, and City
 Commission have all approved the property's reuse, with definitive
 conditions in the PUD & PD to protect the "character of the surrounding
 area."



- Whether reasonable measures can be taken to save the building, structure or object from collapse; and
- √ Two (2) professional structural engineers and a licensed building contractor have inspected the house and deemed it a dangerous building.

Evidence of Structural Damage



Major damage to floor joists

 Hole in the roof large enough to let daylight through





Evidence of Structural Damage



 Roof leak has caused major damage to rafters

 Moisture intrusion, gaps between door frames and walls, algae stains








Demolition. A decision by the historic preservation board approving or denying a certificate of appropriateness for the demolition of buildings, structures or objects other than those in the Pleasant Street Historic District shall be guided by:

7. Whether the building, structure or object is capable of earning reasonable economic return on its

value.



- ➤ With the entire \$139,800 property and structure needing either complete systems or major rehabilitation and renovation, a further investment of nearly \$200,000 would be needed.
- ➤ That fact, coupled with roof removal and rebuilding = \$35,000, moving the structure = \$61,000, and permits = \$24,000 renders the property unable to earn reasonable economic return on a comparable market value for sale.

- 11. All mechanical, (HVAC, Electrical, Plumbing, & Appliances)
- 10. Insulation
- 9. Doors & Windows
- 8. Interior Plaster
- 7. Exterior Brick
- 6. Roofing
- 5. Framing
- 4. Flooring
- 3. Beams & Joists
- 2. Stem Wall
- 1. Foundation




- 7. Whether the building, structure or object is capable of earning reasonable economic return on its value.
- Assuming the house was in excellent condition, the rent that could be achieved would be approximately \$1,200/month.
- If you assume 100% occupancy over the year (which is rarely the case) the annual rent would be \$14,400.
- From that, you need to deduct:
 - Real estate taxes (\$3,338/yr);
 - Property insurance (approximately \$1,200 /yr); and
 - Operating expenses estimated at \$3,000/yr. (lawn care, repairs and maintenance, management fees, extermination, real estate leasing commissions, etc.)
- Based on the above, the annual net rental operating income would be <\$6,862 /year, which would not repay incurred debt.</p>



Recommendation



- Professional City Staff recommends approval with conditions;
- The Applicant has met the Burden of Proof and delivered Competent Substantial Evidence; and
- Applicant requests the City Commission approve demolition of the residential structure at 1227 NW 4th Avenue.



City Commission

Appeal

April 2, 2015

Demolition of a single structure at 1227 NW 4th Avenue



PAUDOEAUX HEWETT, & WALPOLE, IND.

Civil Engineering Land Surveying Land Planning Construction Engineering Inspection

City of Gainesville LDR 30-112 Criteria



Both the City's Land Development Code Section 30-112 and the Historic Preservation Rehabilitation and Design Guidelines manual identify criteria to evaluate new construction within historic districts. This analysis documents the approved redevelopment project and necessity for demolition of a dangerous residential structure. The 2104 Draft Florida Building Code, which should be adopted in March 2015, defines "Dangerous" as:

Any building, structure or portion thereof that meets any of the condition as described below shall be deemed dangerous:

- 1. The building or structure has collapsed, has partially collapsed, has moved off its foundation or lacks the necessary support of the ground.
- 2. There exists a significant risk of collapse, detachment or dislodgement of any portion, member, appurtenance or ornamentation of the building or structure under service loads.