

STATE OF FLORIDA
DEPARTMENT OF STATE
Division of Archives, History
and Records Management
DS-HSP-3AAA Rev. 3-79

FLORIDA MASTER SITE FILE Site Inventory Form

FDAHRM 802 = =
1009 = =

Site Name _____ 830 = = Site No. 8 AL 1136
Survey Date 8007 820 = =
Address of Site: 1021 SW 3rd Ave 905 = =
Instruction for locating _____

(see tax roll no. 13098) 813 = =
Location: University Heights 5 16 868 = =
subdivision name block no. lot no.

County: Alachua 808 = =

Owner of Site: Name: Hanna, P.L. and Cornelia ;
Address: 1523 NW 12th Rd
Gainesville, FL 902 = =

Type of Ownership private 848 = = Recording Date _____ 832 = =

Recorder:
Name & Title: Ann DeRosa Byrne, (Consultant) ;

Address: The History Group 300 W. Peachtree St.
Suite 16 DE Atlanta, Ga. 30308 818 = =

Condition of Site: Integrity of Site: Original Use private residence 838 = =

Check One Check One or More Present Use private residence 850 = =

☐ Excellent 863 = = ☐ Altered 858 = = Dates: Beginning _____ 844 = =

☒ Good 863 = = ☐ Unaltered 858 = = Culture/Phase American 840 = =

☐ Fair 863 = = ☐ Original Site 858 = = Period 20th century 845 = =

☐ Deteriorated 863 = = ☐ Restored () (Date: X) 858 = =

☐ Moved () (Date: X) 858 = =

NR Classification Category: building 916 = =

Threats to Site:

Check One or More

☐ Zoning (X) 878 = = ☐ Transportation (X) 878 = =

☐ Development (X) 878 = = ☐ Fill (X) 878 = =

☐ Deterioration (X) 878 = = ☐ Dredge (X) 878 = =

☐ Borrowing (X) 878 = =

☐ Other (See Remarks Below): _____ 878 = =

Areas of Significance: architecture, local history 910 = =


Significance:

Small Craftsman cottage with predominant gable entry porch, fieldstone
siding. House is located in University Heights subdivision, platted
1912.

SEE SITE FILE STAFF FOR
ORIGINAL PHOTO(S) OR MAP(S)

911 = =

ARCHITECT _____ 872 = =
 BUILDER _____ 874 = =
 STYLE AND/OR PERIOD Craftsman 964 = =
 PLAN TYPE rectangular 966 = =
 EXTERIOR FABRIC(S) masonry: fieldstone 854 = =
 STRUCTURAL SYSTEM(S) wood frame: balloon 856 = =
 PORCHES _____
 _____ 942 = =
 FOUNDATION: unknown 942 = =
 ROOF TYPE: gable 942 = =
 SECONDARY ROOF STRUCTURE(S): entry portico: gable 942 = =
 CHIMNEY LOCATION: east wall 942 = =
 WINDOW TYPE: DHS, 6/6, wood 942 = =
 CHIMNEY: fieldstone 882 = =
 ROOF SURFACING: composition 882 = =
 ORNAMENT EXTERIOR: _____ 882 = =
 NO. OF CHIMNEYS 1 952 = = NO. OF STORIES 1 950 = =
 NO. OF DORMERS _____ 954 = =
 Map Reference (incl. scale & date) _____
 _____ 809 = =
 Latitude and Longitude: _____
 _____ 800 = =
 Site Size (Approx. Acreage of Property): LT 1 833 = =



Township	Range	Section	
10S	20E	05	812 = =
UTM Coordinates:			
Zone	Easting	Northing	890 = =

Photographic Records Numbers 14D3 860 = =

Contact Print

