



New roof with  
architectural  
shingles

Removal of damaged  
gutters

New  
doors


Removal and  
replacement of  
screen  
enclosure

Pressure cleaning and Paint  
of exterior

Removal of tree  
overhanging house

Mulch, Plants and Sod as need  
to update lawn

Pressure  
cleaning of  
driveway,  
sidewalk and  
carport

The image shows the exterior of a house with a light-colored stucco finish. There are several vertical cracks running down the wall. A window with a dark frame is visible. The roofline is dark, and there are trees in the background. The ground is covered with dark mulch and some green plants.

Pressure cleaning  
and paint of all  
exterior trim and  
walls

Removal of much of  
the old landscaping  
and replace with new

New A/C unit

Removal of gutters

Replacement of  
doors

Removal of all  
existing trash

Removal of 2 trees  
that are overhanging  
house. Roots from  
these trees are  
causing damage to  
the foundation to the  
house



Removal of  
gutters

Removal/  
replacement  
of screen  
enclosure

Replacement of  
doors



Remove gutters

Remove, repair or  
replace all damaged  
exterior finishes

Removal and  
replacement of many  
of the old  
landscaping plants

